


97 series solder type

how to order

Example of part number for solder type connectors is given below.



Technical drawing of a circular mechanical component, likely a flange or a mounting plate. The drawing shows a top-down view with a central circular hole. The component has a flange with a raised rim. Dimension lines are present: a horizontal line labeled 'A' indicates the overall diameter of the component, and a vertical line labeled 'B' indicates the overall height or thickness of the flange. The drawing is a line drawing with no shading.

TAB.